THE PRINCIS			· . Te ( f the with a the f the f	POST CONTRACTOR SERVICE SERVICE CONTRACTOR SERVICE SERVICE SERVICE SERVICE SERVICE SERVIC
Approved For Release 2	2002/10/ <b>253/EIA</b> -RDF	34B00836R0	7100040050-1	9 005+7
DAME:	SECRE	T   2   3   3	DOSA	PO TO SERVICE OF THE PROPERTY OF THE SERVICE OF THE
	三····································	<u> </u>	DEA	12 The common termination of the 12 The common termination of the 12
10 3		6 7	CONTRACTOR OF THE PROPERTY OF	THE CONTRACT OF THE PARTY OF TH
FROM \$		8.		
ACTIONS				
info t		50. 91.04 50. 91.04	A 人の地で公司内原治症者 4.13年2.14元の機能 4.13年2月1日 - 13年2月1日 - 13年3月1日 - 13年3	
i		ч •		
ING4011	OSA 1-2	ng ng ng ng Too ren da awaki sekumpan nu awaki Ng ng	*** (1、 本本社 Aができる アンドキャ できま 不可能 (日本社会 A A A A A A A A A A A A A A A A A A A	THE STATE OF THE S
SECRET 290459Z CI			<b>CITE</b>	
PRIORITY INFO				
IDEALIST MAINT-LOGS LOV	ы рі ос			
	W DEOC			
FR ON				

25X1

25X1

25X1

25X1

- 1. PHYSICAL INSPECTION OF ENGINE 611434 REVEALS A HIGH DEGREE OF IMPACT DAMAGE. BOTH INTERMEDIATE AND DIFFUSER CASES WERE SPLIT OPEN. THE N2 GEARBOX WAS SHEARED OFF AND BROKEN IN SEVERAL PIECES. ALL N2 ACCESSORIES WERE BROKEN OFF FROM THEIR MOUNTING FLANGES. THE COMBUSTION CHAMBER CASE WAS CAVED IN DUE TO IMPACT DAMAGE AND WAS REMOVED BY CUTTING WITH A WELDING TORCH. REMOVAL OF THE BURNER CANS REVEALED THE FOLLOWING:
- A. ALL FIRST STAGE TURBINE NOZZLE GUIDE BANES WERE IN THE BOTTOM OF THE NOZZLE CASE, A FEW WERE FOUND IN THE NBR 4 AND NBR 5 BURNER CANS.
- B. FOUR ADJACENT FIRST STAGE TURBINE DISK CHRISTMAS TREE.

  RETAINING SEGMENTS FAILED RELEASING FIVE FIRST STAGE TURBINE

  BLADES. THE REMAINING FIRST STAGE TURBINE BLADES HAVE APPROXI-

S F. C R F. T

Approved For Release 2002/10/25: CIA-RDP74B00836R000100040050-T

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

25X1

PAGE 2 SECRET 64011

MATELY ONE TO ONE AND A HALF INCHES OF BLADE TIPS MISSING.

DISK FAILURE APPEARS SIMILAR TO FAILURE IN ENGINE 661515.

- C. SECOND AND THIRD STAGE TURBINE BLADES ALL HAVE
  APPROXIMATELY ONE TO TWO INCHES OF BLADE TIPS MISSING, THE
  COMPLETE TURBINE SECTION HAS HEAVY FOD TYPE DAMAGE.
- D. FROM WHAT COULD BE INSPECTED THE FIFTEENTH STAGE EXIT VANES WEPE INTACT AND APPEARED SATISFACTORY.
- E. REMOVAL OF THE NBR 6 BEARING HEATSHIELD DISHPAN
  REVEALED BOTH OIL PRESSURE AND SCAGENGE TUBES BROKEN OFF. THIS
  APPEARS TO BE THE RESULT OF ENGINE VIBRATION FOLLOWING DISK
  FAILURE.
- 2. THE ENGINE IS NOW READY FOR AIRLIFT TO PWA EAST COAST FOR FURTHER INVESTIGATION. THE BURNER CANS, N2 GEARBOX SECTIONS AND ENGINE ACCESSORIES ARE BOXED AND WILL ACCOMPANY THE ENGINE. THE REMAINING PARTS OF THE FIVE FIRST STAGE TURBINE BLADES ARE IN A BAG TIED TO THE FUEL NOZZLES.

  S E C R E T TOR: 290538Z JUN 66